

PRODUCT DISCONTINUATION NOTICE

Production of the following products has been discontinued

HP50TA & HP50HA1 AG Heat Pumps



Both models to be replaced with models using better user interface and newer technology providing a higher heat output.

HP50HA1 already replaced by HP50HA2.



**Discontinued from:
March 30, 2020**

Discontinued:	HP50HA1 / HP50TA
Replacement:	HP50HA2

For more information on options and availability of replacement parts, please contact Hayward/IMG at Fax: 909.444.0327, email: img@hayward.com