

PRODUCT DISCONTINUATION NOTICE

The production of the following product line has been discontinued

SUPER II PUMP US AZ SERIES



The impending DOE rule change in July 2021 restricts our ability to produce AZ Series Super II pumps as they are non-compliant.

**Discontinued from:
Jan 2021**

**Last order in by:
Jan 25 2021**

Discontinued Models	Replacement Options
SP3005x7AZ	SP32900VSP
SP3007x10AZ	SP32900VSP
SP3010x15AZ	SP32900VSP
SP3015x20AZ	SP32900VSP
SP3020x25AZ	SP32950VSP
SP3025x30AZ	SP3250EE

For more information on options and availability of replacement parts, please contact Hayward/IMG at Fax: 909.444.0327, email: img@hayward.com