

PRODUCT DISCONTINUATION NOTICE

The production of the following product line has been discontinued

TRISTAR PUMP 50Hz US SERIES



Due to insufficient volumes and the availability of alternative 50Hz pumps from Hayward Europe we have discontinued the production of 50Hz Tristar Series pumps in the US.

The impending DOE rule change in July 2021 also restricts our ability to produce the single speed Tristar pumps.

**Discontinued from:
Jan 2020**

Discontinued Models	Alternative models – Super II US	Alternative models – Tristar Europe
SP3205x751	-	SP32081
SP3207x1051	SP3007x1051	SP32111
SP3210x1551	SP3010x1551	SP32161
SP3215x2051	SP3015x2051	SP32201
SP3225x3051	SP3025x30G51	SP32301
SP3225x3053	SP303053	SP32303

For more information on options and availability of replacement parts, please contact Hayward/IMG at Fax: 909.444.0327, email: img@hayward.com